Printed Pages: 03								
Paper Id:	120416							

Sub Code: REE409											
Roll No.											

**D D D** 400

**B TECH** 

# (SEM IV) THEORY EXAMINATION 2017-18 ELECTRICAL MACHINES AND CONTROLS

MM.-70

#### SECTION A

Q.1-Attempt all the question: -

- a) Write down the equation for frequency of emf induced in an Alternator.
- **b**) Why are Alternators rated in kVA and not in kW?
- c) What is meant by armature reaction in Alternators?
- d) What is meant by synchronous impedance of an Alternator?
- e) Name the various methods for predetermining the voltage regulation of 3-phase Alternator.
- f) What are different types of Control Systems?
- g) For the system in the given figure the characteristic equation is



### **SECTION B**

Q.2- Attempt any *three* questions

- a) A 10 KVA, 200/400 V, 50 Hz, single phase transformer gave the following test results: Open circuit testfrom L.V. side: 200 V, 1.3 A, 120 W
  Short circuit test from H.V. side: 22 V, 30 A, 200 W
  - i. Draw the equivalent circuit of the transformer referred to H.V. side.
  - ii. The efficiency of the transformer at 90% loading with load 0.8 power factor.
- a) What is an autotransformer? State its merits and demerits over two winding transformer. An 1100/2200 V single phase transformer is rated at 1000KVA; if the two winding are connected in series to form an autotransformer determine its voltage and power.
- b) Why is starter necessary for starting of a dc motor? Explain briefly working of 3-point starter. A 220 V d.c. shunt motor having an armature resistance of 0.25  $\Omega$  carries an armature current of 50 A and runs at 600 r.p.m. if the flux is reduced by 1% by field regulator, find the speed of motor, assuming the torque to remain same.
- c) Derive the equation for the torque developed by a 3-phase induction motor. Draw a typical torque-slip curve and deduce the condition for maximum torque.
- d) Determine the voltage regulation of 3-phase, star connected alternator of terminal voltage  $2000\sqrt{3}$  Volt producing a current of 100 A at
  - (i) 0.8 load p.f. lagging
    - (ii) 0.707 p.f. leading

The full load current of 100 A is produced on short-circuit test on a field excitation of 2.5 Amp. An emf of 500 V is generated on open circuit test on the same excitation current of 2.5 Amp. (Given  $R_a = 0.8 \Omega$ )

(7\*3=21)

(2\*7=14)

TIME: 3:00HRS

#### SECTION C

#### Q.3- Attempt any one questions

- a) What is two-phase servomotor? Draw its torque-speed characteristics for various control voltages.
- b) A unity feedback control system  $G(s) = \frac{K(s+1)(s+2)}{(s+0.1)(s-1)}$  has an open loop transfer function. Using the Routh stability criterion, determine the range of value of K for which the close loop

Using the Routh stability criterion, determine the range of value of K for which the close loop system has 0, 1 or 2 poles in the right half of s-plane.

#### Q.4- Attempt any one questions

a) For the system shown below, determine the values of gain K and velocity feedback constant  $K_h$  so that the maximum overshoot is 0.2 and the peak time is 1 sec. With the obtained values of K and  $K_h$ , obtained the rise time and settling time.



**b)** Differentiate between open loop and closed loop system with suitable examples. What are the advantages of feed-back?

## Q.5- Attempt any one questions

(7\*1=7)

a) Obtain the differential equation of the mechanical system and Sketch the mechanical equivalent representation for the system shown below.



b) A unity feedback system has an open-loop transfer function

 $G(s) = \frac{K}{s(s^2 + 4s + 13)}$ . Sketch the root locus plot of the system determining the following:--

- (i) Centroid, number and angle of asymptotes.
- (ii) Break away point if any
- (iii) The value of K and the frequency at which the root locus cross the  $j\omega$ -axis.
- (iv) Angle of departure of root locus from the poles

#### Q.6- Attempt any one questions

a) Discuss the affect of following controllers on the second order control system:

- (i) PI controller
- (ii) PD controller
- (iii) Rate-feedback controller.

(7\*1=7)

### (7\*1=7)

(7\*1=7)

b) Consider the system with the following open loop Transfer function

 $G(S) = \frac{K}{S(T_1 S + 1)(T_2 S + 1)}$ 

Determine stability of system using NyquistCriterian for

- i) the gain K is small.
- ii) The gain K is large

# Q.7- Attempt any one questions

(7\*1=7)

**a)** Draw the Bode plot for the transfer function

$$G(s) = \frac{75(1+0.2s)}{s(s^2+16s+100)}$$

- (i) Gain cross over frequency
- (ii) Phase cross over frequency
- (iii) Gain Margin and Phase margin
- (iv) Stability of the given system
- **b)** Determine the resonant frequency wr, resonant peak Mp and Bandwidth of system whose T.F is given by

$$C(S) = 5$$
  
 $K(S) = 5$   
 $S^2 + 2S + 1$